

FAA-04-19203-3

298060

Aircraft Certification Service

Transport Airplane Directorate "Short" Domestic Worksheet 2004-NM-109-AD

Frequency Converter No Output Short Circuit Protection

DOCKET NUMBER:

TECH WRITER:

ANSP Board: 11/21/01

Manufacturer's Service Information/Revision/Date (Attach 2 clean copies):

PROPOSED CORRESPONDING ACTION:☐ Emergency AD

Is this action one of the following?

☐ Immediately Adopted AD☐ Supersedure of AD☒ Notice of Proposed Rulemaking☐ Revision of AD (Docket No. TBD)☐ Final rule after NPRM☐ Supplemental NPRM (Docket No. TBD)

(If FRAN, complete Attachment A.)

(If any of the above is checked, complete Attachment B.)

☐ Other (No-Notice Final Rule)

RECEIVED

MAY 19 2004

ANM-114

ACO Project Engineer Name/Title:

Binh V. Tran / Aerospace Engineer

Branch: ANM-130S

Telephone:

425-917-6485

Backup Engineer:

Telephone:

1. Model, Applicability, # Airplanes (both U.S. & worldwide) - Refer to SB; state any differences for this AD:

Model: 757-200

Applicability: See Boeing Service Bulletin 757-25-0255, Revision 0, dated December 11, 2003

Concurrent 757-24-0093-8/14/03

U.S. airplanes: 4

worldwide airplanes: 4

Source:

AD Summary and Discussion Sections:**2. What has the manufacturer told the FAA?***"The FAA has received reports indicating that..."*

Describe background/events that prompted the AD in 1-2 sentences. Refer to SB 'Reason.'

Boeing analysis has shown that a hard short condition between the output of frequency converter and its downstream circuit breaker will produce a continuous current of 55 amps, causing the undersized output wiring to exceed its wire temperature rating of 150 degree C

2004 SEP 29 A 11:04

DEPT OF TRANSPORTATION
FAA/CTA

3a. What is the unsafe condition AND its cause?

"These actions are intended to prevent..."

Describe unsafe condition and its cause in 2-3 sentences (non-technical terms). Refer to SB 'Reason.'

Frequency Converter has no output short circuit protection, may cause overheat condition.

3b. What is the end-level effect on the airplane?

"...which could result in..."

Provide a 1-sentence description; use non-technical terms.

If the output of Frequency Converters is shorted, it will overheat, potential causing a wire bundle failure. The bundle failure may affect other systems sharing the impacted bundle.

AD Relevant Service Information Section:

4. (Yes or No) Is the corrective action required in this AD considered to be interim action?

NO

5. (Yes or No) Is this action considered 'sensitive', or is it related to a Safety Recommendation?

(If yes, state why sensitive, and/or provide copy of FAA/NSTB Safety Recommendation.)

NO

6. Does the referenced service document include reference to an "operator's equivalent procedure?"

[If yes, specify whether that procedure employed by the operator (even if not technically 'equivalent') adequately addresses the identified unsafe condition and provides an acceptable level of safety.]

NO YES - Acceptable for

7. AD Differences Section (if needed):

"This AD differs from the SB

Check if: Flight with Cracks _____ Mandate Terminating Action _____ Contact Mgr, FAA _____
Compliance time _____ Mandate AFM Action _____

Describe any other differences between service bulletin and this proposed FAA AD.

None

AD Cost Impact Section:

8a. Work hours for corrective action(s) required: (List hours or reference SB 'Manpower').

105 hours per airplane

8b. Parts Cost, if any: (List costs or reference SB 'Material - Cost and Availability').

\$11,000.00 per airplane

9. AD Body Section:

For EACH corrective action, mark up SB, if usable -OR- fill out Corrective Action Table below.

9a: Action # 1

What is the corrective action? Replace three frequency converters part number 1-002-0102-0730 with new part number 1-002-0102-2031, install three relay assemblies with power cut-off relays and a thermal switch in closet assembly S3, change the wires with higher permitted temperature. All the above activities to be performed according to Boeing Service Bulletin 757-25-0255, Rev New, dated December 11, 2003. *SIB 757-24-0093 must be accomplished prior to or concurrence with this SIB.*

What is its compliance time? Within 18 months from the effective date of this AD.

(Add grace period if not available)

What is repetitive interval? N/A

9b: Action # 2

What is the corrective action?

What is its compliance time?

(Add grace period if not available)

What is repetitive interval?

10. (Yes or No) Should corrective action(s) required in this AD to be applied to spares as well?

NO ? Page 22

11. Should a ferry flight permit be: ☒ Permitted ☐ Permitted with limitations* ☐ Prohibited ☐

*List limitations.

12. With whom outside the FAA has this proposal been discussed (i.e. ATA, RAA, ALPA, etc.)?

NOTE: This item should be completed prior to submission of the AD Proposal Worksheet.

Organization

BACG

ATA

Person Contacted

David Nguyen

Charlie Bautz

Date

11/02

01/13/04

Reaction

Concurrence

Concurrence

13. Check the appropriate response:

Yes ☐ No ☒ Does this action affect the Presidential fleet?

Yes ☐ No ☒ Does this action affect the FAA fleet?

Yes ☐ No ☒ Was this action prompted by the use of suspected unapproved parts (SUP)?

14. Check the category that best describes the cause of the unsafe condition addressed by this AD:

<input checked="" type="checkbox"/> Design Problem	<input type="checkbox"/> Unapproved Parts	<input type="checkbox"/> Operational
<input type="checkbox"/> Maintenance	<input type="checkbox"/> Quality Control Problem**	<input type="checkbox"/> Other (specify): _____
	<input type="checkbox"/> **Reporting Req't Needed?	_____

4/2/2004

F:\AD\Frequency converter757.DOC